

FIG. 1A

ANT. LATERAL APPROACH TO FEMUR





FIG. 1B

EXPOSED FEMUR



FIG. 1C

PLACEMENT OF FIXATOR PLATE



20071496 - 020702

FIG. 2A

CREATION OF GAP DEFECT





FIG. 2B

POST-IMPLANTATION OF BONE ALLOGRAFT



2020/08/08 02202020

FIG. 3A



MIGRATION OF BONE ALLOGRAFT IN ALGINATE (-Ca²⁺)

FIG. 3B

BONE ALLOGRAFT IS RETAINED WITH ADDITION OF Ca^{2+}



J0071190-020702


FIG. 4A

12 WK UNFILLED DEFECT



FIG. 4B

12 WK ALGINATE CARRIER ALONE



10071190.020202

FIG. 5

12 WK DBM IN HA + VEGF




FIG. 6

12 WK DBM IN HA+VEGF

